UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,803,614 B2

Page 1 of 1

DATED

: October 12, 2004 INVENTOR(S) : Hidekazu Takahashi

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page,

Item [57], ABSTRACT,

Line 6, "An" should read -- an --.

Drawings,

Sheet 6, Figure 6, item 310, "OPERATTION" should read -- OPERATION --.

Column 1,

Line 53, "sown" should read -- shown --.

Column 5,

Line 12, "a intrinsic" should read -- an intrinsic --.

Column 6.

Line 36, "total-control" should read -- total control --.

Column 7.

Line 5, "filer" should read -- filter --.

Signed and Sealed this

Twenty-second Day of February, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office